

ProTEQ

HVAC COIL COATINGS

ProTEQ offers a 60 month warranty on all new fin/tube coils from date of application, 24 month for clear coated panel treatment.

Terms and conditions:

- Coils should only be cleaned with water and/or a non-acidic, neutral Ph cleaning product, i.e. soapy solution, with low water pressure.
- Coils within 10 km from the coast should be cleaned every 3-6 months and once annually outside the 10 km area, recorded by an approved air conditioner servicing company.
- Coils exposed to constant marine conditions require cleaning monthly.

This warranty does not cover:

- Any other internal components other than the coil
- Damage from improper cleaning methods, i.e. incorrect cleaning products, and the use of improper tools i.e. wire brushes or sharp objects
- Incorrect fitment, repair or any other activity not related to the ProTEQ Treatment
- Internal damage caused by incorrect gas or corrosive liquids

Re-coating does not extend the warranty on the unit. ProTEQ reserves the right to inspect any damage prior to re-coat and will not be held liable by failure of equipment in operation or damages, profit loss and property damage caused by it. Completed maintenance log sheets are to be produced on inspection.